Babytherm 8004/8010
Technical Service Bulletin # 4 A

Re: **Modification of photo-therapy option**

Date: March 8, 2001

Reference Doc: Service Bulletins from Dräger Medizintechnik GmbH:
6132.200 Babytherm 8004/8010 # 4, November 30, 2000

Reason: Dräger Medizintechnik GmbH has released a modification to the photo-therapy option.

Solution: Replace plastic cable ties with metal cable ties.

Devices affected: All units Babytherm 8004 and Babytherm 8010 with installed option phototherapy shipped prior March 2001 not labeled with "APT 2000" or "ATP 2000" (Advanced Phototherapy 2000) on the back of the radiant heater:



These are devices with the following serial numbers in the USA and Canada:

ARLx - xxxx	(1997)
ARMx - xxxx	(1998)
ARNx - xxxx	(1999)
ARPx - xxxx	(2000)

When: As soon as possible.

Reporting: To Dräger Medical, Inc. by Fax 1-215-721-5784.
A Feedback Form is included in the conversion kit.

Additional Info: Time needed for the modification is approx. 1.5 hours.

Cost: Free of charge.

Ordering Info:

Conversion kit "Photo therapy cable clip"	P/N 2M 30 438
Loctite 221	P/N 79 01 966
or	
Loctite 222	P/N 79 10 445

Distribution: Dräger Service Personnel, Authorized Service Organizations, and trained hospital technicians for Babytherm 8004/8010.

If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789.

Dräger Medical, Inc.
Technical Product Manager